

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Semi-Annual	<b>Date:</b> 8/22/2023	<b>Time:</b> 9:29 AM
<b>Name of School Corporation:</b> CROTHERSVILLE COMM. SCHOOLS	<b>Corp ID:</b> 363710	
<b>Address of School Corporation:</b> 201 S Preston St		
<b>City:</b> Crothersville	<b>Zip:</b> 47229	<b>County Number:</b> 36
<b>VIN:</b> 4DRAPSKK0DB043219	<b>License Number:</b> 9260	<b>Bus Number:</b> 16
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2011	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2011	<b>Mileage:</b> 43526	<b>Year:</b> 2011
<b>Bus Type:</b> C		
<b>Inspection Status:</b> R	<b>Inspected By:</b> Seth Davidson	<b>PE:</b> 8101

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
17-1-1	Any dome light is inoperative
20-1-10	See Notes: Any defect inspector deems a violation not listed
59-1-15	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**