

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	8/24/2023	Time:	8:06 AM
Name of School Corporation:	BATESVILLE COMM. SCHOOL CORP.			Corp ID:	696895
Address of School Corporation:	626 N Huntersville Rd				
City:	Batesville	Zip:	47006	County Number:	69
VIN:	1T88T9E2XD1160958	License Number:	5020	Bus Number:	3
Make of Body:	Thomas Built Buses, Inc.	Year:	2012	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D			Mileage:	63413
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

### Violations - Out of Service

#### Inspection Code Description

#### Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.