

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	8/25/2023	Time:	1:45 PM		
Name of School Corporation:	PERU COMMUNITY SCHOOLS			Corp ID:	525635		
Address of School Corporation:	35 W 3rd St						
City:	Peru	Zip:	46970	County Number:	52		
VIN:	4UZABRFC5RCUD2445		License Number:	25967	Bus Number:	4	
Make of Body:	Thomas Built Buses, Inc.	Year:	2022	Make of Chassis:	Freightliner	Year:	2024
Bus Type:	C			Mileage:	18499		
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
51-1-1	Any door seals are missing, damaged, or torn
70-1-7	Any emergency window is too difficult to open

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement
51-2-1	The service door does not open or close properly

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.