

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	8/29/2023	Time:	8:56 AM
Name of School Corporation:	BARTHOLOMEW CONS. SCHOOL CORP.			Corp ID:	30365
Address of School Corporation:	1260 N Marr Rd				
City:	Columbus	Zip:	47201	County Number:	3
VIN:	4UZABRFC4MCMF5062	License Number:	23898	Bus Number:	213
Make of Body:	Thomas Built Buses, Inc.	Year:	2019	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	C			Mileage:	34226
Inspection Status:	O	Inspected By:	Seth Davidson	PE:	8101

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-6	Bumper thickness measures less than 3/16ths of an inch
82-1-2	See Notes: Any defect inspector deems a violation not listed

## Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

## Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.