REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection			**Date:**	8/29/2023	**Time:**	8:56 AM
Name of School Corporation:		BARTHOLOMEW CONS. SCHOOL CORP.				**Corp ID:**	30365
Address of School Corporation:		1260 N Marr Rd					
City:	Columbus	**Zip:**	47201			**County Number:**	3
VIN:	4UZABRFC4MCMF5062			**License Number:**	23898	**Bus Number:**	213
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2019	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2021
Bus Type:	C			**Mileage:**	34226		
Inspection Status:	O	**Inspected By:**	Seth Davidson			**PE:**	8101

Violations - Rejected

Inspection Code	Description
11-1-6	Bumper thickness measures less than 3/16ths of an inch
82-1-2	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.