

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Semi-Annual	<b>Date:</b> 9/12/2023	<b>Time:</b> 8:39 AM	
<b>Name of School Corporation:</b> SOUTH DEARBORN COMM. SCH. CORP	<b>Corp ID:</b> 151600		
<b>Address of School Corporation:</b> 6109 Squire Place			
<b>City:</b> Aurora	<b>Zip:</b> 47001	<b>County Number:</b> 15	
<b>VIN:</b> 4UZAAXCS17CW45090	<b>License Number:</b> B261R	<b>Bus Number:</b> 2	
<b>Make of Body:</b> Freightliner	<b>Year:</b> 2007	<b>Make of Chassis:</b> Freightliner	<b>Year:</b> 2007
<b>Bus Type:</b> B	<b>Mileage:</b> 129377		
<b>Inspection Status:</b> A	<b>Inspected By:</b> Chris Clark	<b>PE:</b> 6665	

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.