

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Semi-Annual      **Date:** 9/13/2023      **Time:** 8:32 AM  
**Name of School Corporation:** A NEW DAWN DAY CARE      **Corp ID:** 1042  
**Address of School Corporation:** 302 Hunterstation Rd  
**City:** Sellersburg      **Zip:** 47172      **County Number:** 10  
**VIN:** 1GBHG31V261178901      **License Number:** B876F      **Bus Number:** 1  
**Make of Body:** Chevrolet      **Year:** 2006      **Make of Chassis:** Chevrolet      **Year:** 2006  
**Bus Type:** A2      **Mileage:** 123899  
**Inspection Status:** O      **Inspected By:** Troy Boyd      **PE:** 5171

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

### Violations - Out of Service

Inspection Code      Description

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**