

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	9/14/2023	<b>Time:</b>	9:32 AM
<b>Name of School Corporation:</b>	HERITAGE HALL CHRISTIAN SCHOOL			<b>Corp ID:</b>	18-PS-HHC
<b>Address of School Corporation:</b>	6401 West River Road				
<b>City:</b>	Muncie	<b>Zip:</b>	47304	<b>County Number:</b>	18
<b>VIN:</b>	1HVBBPLP2NH447968	<b>License Number:</b>	B246AD	<b>Bus Number:</b>	5
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	1992	<b>Make of Chassis:</b>	IC Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	246824	<b>Year:</b>	1992
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Steve Spallinger	<b>PE:</b>	6921

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
46-1-1	Any seat is loose from the floor or seat rail
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
30-1-2	There are weak areas due to deterioration

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**