## REPORT OF SCHOOL BUS INSPECTION

Type of 11:26 Semi-Annual Time: Date: 9/14/2023 Inspection: AM MARION COMMUNITY SCHOOLS Name of School Corporation: Corp ID: 272865 **Address of School Corporation:** 826 E 30th St County City: Marion Zip: 46952 27 Number: License VIN: 1BAKJCPA1CF285518 2297 **Bus Number:** 19 Number: Make of Blue Bird Blue Bird Make of Body: Year: 2011 2012 Year: Corporation Chassis: Corporation **Bus Type:** С Mileage: 85212 Inspection Inspected 0 PE: Randy McPike 7018 Status: By:

## **Violations - Rejected**

| Inspection<br>Code | <u>Description</u>   |
|--------------------|--|
| 46-1-3             | Any required padding is missing  |
| 28-1-4             | The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction. |

## **Violations - Out of Service**

| Inspection<br>Code | <u>Description</u>  |
|--------------------|---|
| 70-2-4             | Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94 |

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.