

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                                |                        |            |                         |                          |
|---------------------------------------|--------------------------------|------------------------|------------|-------------------------|--------------------------|
| <b>Type of Inspection:</b>            | Post-Crash Inspection          | <b>Date:</b>           | 9/15/2023  | <b>Time:</b>            | 9:19 AM                  |
| <b>Name of School Corporation:</b>    | MONROE COUNTY COMM. SCH. CORP. | <b>Corp ID:</b>        | 535740     |                         |                          |
| <b>Address of School Corporation:</b> | 505 E North Dr                 |                        |            |                         |                          |
| <b>City:</b>                          | Bloomington                    | <b>Zip:</b>            | 47401      | <b>County Number:</b>   | 53                       |
| <b>VIN:</b>                           | 4UZAEXG47PCUE8498              | <b>License Number:</b> | 25711      | <b>Bus Number:</b>      | EV5                      |
| <b>Make of Body:</b>                  | Thomas Built Buses, Inc.       | <b>Year:</b>           | 2022       | <b>Make of Chassis:</b> | Thomas Built Buses, Inc. |
| <b>Bus Type:</b>                      | C                              | <b>Mileage:</b>        | 14037      | <b>Year:</b>            | 2023                     |
| <b>Inspection Status:</b>             | O                              | <b>Inspected By:</b>   | Mike Adams | <b>PE:</b>              | 7407                     |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 31-1-1                 | There are loose or missing bolts or rivets where front and rear spring hangers are attached to the frame |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>                                      |
|------------------------|---|
| 31-2-1                 | Frame is deteriorated, cracked, broken or severely bent |

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**