## REPORT OF SCHOOL BUS INSPECTION

Type of Time: Spot Checks Date: 9/15/2023 10:24 AM Inspection:

Name of School Corporation: MARION COMMUNITY SCHOOLS 272865 Corp ID:

**Address of School Corporation:** 826 E 30th St

City: Marion Zip: 46952 **County Number: 27** VIN: 4DRBUC8N5RB282695 License Number: 26115 Bus Number: 36 IC Year: 2023

2024

Make of Body: Make of Chassis: IC Corporation Year: Corporation

Inspection Status: R PE: 7018 Inspected By: Randy McPike

Mileage:

4114

## **Violations - Rejected**

Bus Type:

<u>Inspection</u> **Description** Code 7-1-3 Air leak at proper connection

The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads 28-1-4 (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2

triangular bandages, 1 instruction.

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.