

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 9/19/2023	<b>Time:</b> 9:33 AM
<b>Name of School Corporation:</b> HONEY GROVE EDUCATIONAL DAYCARE		<b>Corp ID:</b> 41001Z
<b>Address of School Corporation:</b> 1709 S SR 135		
<b>City:</b> Greenwood	<b>Zip:</b> 46143	<b>County Number:</b> 41
<b>VIN:</b> 1GBHG31RXX1146766	<b>License Number:</b> B958AB	<b>Bus Number:</b> 2
<b>Make of Body:</b> Chevrolet	<b>Year:</b> 1999	<b>Make of Chassis:</b> Chevrolet
		<b>Year:</b> 1999
<b>Bus Type:</b>	<b>Mileage:</b> 129640	
<b>Inspection Status:</b> R	<b>Inspected By:</b> Joel Flores	<b>PE:</b> 7415

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description