

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Post-Crash Inspection **Date:** 9/19/2023 **Time:** 10:34 AM  
**Name of School Corporation:** NORTH CENTRAL PARKE COMM SCH CORP **Corp ID:** 616375  
**Address of School Corporation:** 1497 E STATE RD 47  
**City:** MARSHALL **Zip:** 47859 **County Number:** 61  
**VIN:** 1FDES8PM2JKB36459 **License Number:** 20521 **Bus Number:** PH6  
**Make of Body:** Ford **Year:** 2018 **Make of Chassis:** Ford **Year:** 2018  
**Bus Type:** A1 **Mileage:** 25824  
**Inspection Status:** O **Inspected By:** Byron Goodman **PE:** 7008

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.