REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 9/19/2023 **Time:** 10:34 AM **Name of School Corporation:** NORTH CENTRAL PARKE COMM SCH CORP **Corp ID:** 616375

Address of School Corporation: 1497 E STATE RD 47

City:MARSHALLZip:47859County Number: 61VIN:1FDES8PM2JKB36459License Number: 20521Bus Number: PH6Make of Body:Ford Year: 2018Make of Chassis: Ford Year: 2018

Bus Type: A1 Mileage: 25824

Inspection Status: O **Inspected By:** Byron Goodman **PE:** 7008

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

11-1-2 The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.