REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection			Date:	9/20/2023	Time:	10:09 AM
Name of School C	orporation:	GREE	ENWOOD CHE	RISTIAN ACADEM	Y	Corp ID:	41b354
Address of Schoo	l Corporation:		835 West Wo	rthsville Rd			
City:	Greenwood		Zip:	46143		County Number:	41
VIN:	1GB0GRBP6P110767	1		License Number:	S159186	Bus Number:	8
Make of Body:	Collins Bus Corporation	Year:	2023	Make of Chassis:	Chevrolet	Year:	2023
Bus Type:	A1			Mileage:	1569		
Inspection Status:	0		Inspected By:	Joel Flores		PE:	7415

Violations - Rejected

Inspection Code	<u>Description</u>			
29-1-4	Prohibited area line is missing or improper			
104-1-1	See Notes: Any defect inspector deems a violation not listed			
57-1-5	Step-well light is missing or inoperative			
49-1-1	The reflective material is placed anywhere other than on the front and rear, or both, of the bus between the warning lamps; each side beltline, seat line, or floor line or all three (3); outlining each required emergency exit; or across the rear of the bus directly above the rear bumper.			
24-1-7	See Notes: Any defect inspector deems a violation not listed			
79-1-5	See Notes: Any defect inspector deems a violation not listed			

Violations - Out of Service

Inspection Code	<u>Description</u>
79-2-1	The handle is missing or unit will not open

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.