

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	9/21/2023	<b>Time:</b>	10:59 AM
<b>Name of School Corporation:</b>	EAST COAST MIGRANT HEAD START AND PROJECT			<b>Corp ID:</b>	
<b>Address of School Corporation:</b>	506-B Pender Street East				
<b>City:</b>	Wilson	<b>Zip:</b>	27893	<b>County Number:</b>	79
<b>VIN:</b>	4DRBUAFL18B555703	<b>License Number:</b>	B853S	<b>Bus Number:</b>	28
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2007	<b>Make of Chassis:</b>	IC Corporation
<b>Year:</b>		<b>Year:</b>		<b>Year:</b>	2008
<b>Bus Type:</b>	C	<b>Mileage:</b>	138121		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Bradley Mlller	<b>PE:</b>	7809

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
67-1-1	Rims and wheels are painted any other color than black or gray. (Aluminum wheels may be of natural color) (MFSAB's are permitted to have factory wheels)
65-1-2	The area around any warning light is not painted black

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**