

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------------|------------------------|---------------|-------------------------|--------------------------|
| Type of Inspection: | Post-Crash Inspection | Date: | 9/22/2023 | Time: | 7:49 AM |
| Name of School Corporation: | BARTHOLOMEW CONS. SCHOOL CORP. | Corp ID: | 30365 | | |
| Address of School Corporation: | 1260 N Marr Rd | | | | |
| City: | Columbus | Zip: | 47201 | County Number: | 3 |
| VIN: | 4UZABRDT8FCGK9227 | License Number: | 8443 | Bus Number: | 155 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2014 | Make of Chassis: | Thomas Built Buses, Inc. |
| Bus Type: | C | Mileage: | 109053 | | |
| Inspection Status: | O | Inspected By: | Seth Davidson | PE: | 8101 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 51-1-4 | See Notes: Any defect inspector deems a violation not listed |
| 63-1-11 | See Notes: Any defect inspector deems a violation not listed |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 51-2-1 | The service door does not open or close properly |
| 24-2-2 | Any body surface protrudes beyond the normal limits of the body structure |
| 24-2-1 | There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)). |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.