

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual	Date: 9/26/2023	Time: 9:23 AM	
Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL	Corp ID: 141375		
Address of School Corporation: 5494 E SR 58			
City: Elnora	Zip: 47529	County Number: 14	
VIN: 4DRBUAFP28B556801	License Number: B399S	Bus Number: 16	
Make of Body: IC Corporation	Year: 2007	Make of Chassis: IC Corporation	Year: 2008
Bus Type: C	Mileage: 103539		
Inspection Status: R	Inspected By: Philip Lubbers	PE: 7703	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
43-1-9	Any unauthorized lettering or markings are present on the body.
68-1-1	Washers do not function properly in any manner

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.