

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	9/26/2023	Time:	9:34 AM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL	Corp ID:	141375		
Address of School Corporation:	5494 E SR 58				
City:	Elnora	Zip:	47529	County Number:	14
VIN:	4DRBUAAP0AB184999	License Number:	B208E	Bus Number:	6
Make of Body:	IC Corporation	Year:	2010	Make of Chassis:	IC Corporation
Bus Type:	A1	Mileage:	194072	Year:	2010
Inspection Status:	R	Inspected By:	Philip Lubbers	PE:	7703

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
63-1-3	Any front tire has less than 4/32 inch tread depth when measured in any two adjacent major grooves
63-1-4	Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves
2-1-1	Required back-up lights do not function.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.