

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual	Date: 9/26/2023	Time: 9:34 AM
Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL	Corp ID: 141375	
Address of School Corporation: 5494 E SR 58		
City: Elnora	Zip: 47529	County Number: 14
VIN: 4DRBUAAP0AB184999	License Number: B208E	Bus Number: 6
Make of Body: IC Corporation	Year: 2010	Make of Chassis: IC Corporation
Year: 2010	Mileage: 194072	PE: 7703
Bus Type: A1	Inspected By: Philip Lubbers	
Inspection Status: R		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
63-1-3	Any front tire has less than 4/32 inch tread depth when measured in any two adjacent major grooves
63-1-4	Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves
2-1-1	Required back-up lights do not function.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.