

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 9/26/2023 Time: 10:46 AM  
Name of School Corporation: PRIMROSE SCHOOL @ GRAY EAGLE Corp ID: 290003  
Address of School Corporation: 12290 Olio Rd.  
City: Fishers Zip: 46037 County Number: 29  
VIN: 1GBHG31V261253225 License Number: B112U Bus Number: 1  
Make of Body: Chevrolet Year: 2006 Make of Chassis: Chevrolet Year: 2006  
Bus Type: A1 Mileage: 28033  
Inspection Status: R Inspected By: Joel Flores PE: 7415

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
49-1-1	The reflective material is placed anywhere other than on the front and rear, or both, of the bus between the warning lamps; each side beltline, seat line, or floor line or all three (3); outlining each required emergency exit; or across the rear of the bus directly above the rear bumper.

### Violations - Out of Service

#### Inspection Code Description

#### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.