REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	9/26/2023	**Time:**	10:46 AM
Name of School Corporation:	PRIMROSE SCHOOL @ GRAY EAGLE			**Corp ID:**	290003
Address of School Corporation:	12290 Olio Rd.				
City:	Fishers	**Zip:**	46037	**County Number:**	29
VIN:	1GBHG31V261253225	**License Number:**	B112U	**Bus Number:**	1
Make of Body:	Chevrolet **Year:** 2006	**Make of Chassis:**	Chevrolet	**Year:**	2006
Bus Type:	A1	**Mileage:**	28033		
Inspection Status:	R	**Inspected By:**	Joel Flores	**PE:**	7415

Violations - Rejected

Inspection Code	Description
49-1-1	The reflective material is placed anywhere other than on the front and rear, or both, of the bus between the warning lamps; each side beltline, seat line, or floor line or all three (3); outlining each required emergency exit; or across the rear of the bus directly above the rear bumper.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**