

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	9/26/2023	<b>Time:</b>	10:11 AM
<b>Name of School Corporation:</b>	FIRST STUDENT - INDPLS			<b>Corp ID:</b>	4981
<b>Address of School Corporation:</b>	xxx				
<b>City:</b>	Indianapolis	<b>Zip:</b>	46202	<b>County Number:</b>	49
<b>VIN:</b>	4DRBUP1N3HB474391	<b>License Number:</b>		<b>Bus Number:</b>	457
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2016	<b>Make of Chassis:</b>	IC Corporation
<b>Year:</b>		<b>Year:</b>		<b>Year:</b>	2017
<b>Bus Type:</b>	C	<b>Mileage:</b>	86720		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Nick Cox	<b>PE:</b>	8795

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-10	See Notes: Any defect inspector deems a violation not listed
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**