

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	9/22/2023	Time:	10:49 AM
Name of School Corporation:	SOUTHWEST PARKE COMM SCH CORP			Corp ID:	616260
Address of School Corporation:	RR 1				
City:	Montezuma	Zip:	47862	County Number:	61
VIN:	4DRBUC8N9LB872177	License Number:	B751Q	Bus Number:	15
Make of Body:	IC Corporation	Year:	2019	Make of Chassis:	IC Corporation
		Year:		Year:	2020
Bus Type:	C	Mileage:	111700		
Inspection Status:	O	Inspected By:	Byron Goodman	PE:	7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-3	There are any breaks, nicks or chips larger than 3/4 inch in diameter in the area covered by the wipers on the drivers' side
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
98-1-13	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.