

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 9/22/2023 **Time:** 10:49 AM
Name of School Corporation: SOUTHWEST PARKE COMM SCH CORP **Corp ID:** 616260
Address of School Corporation: RR 1
City: Montezuma **Zip:** 47862 **County Number:** 61
VIN: 4DRBUC8N9LB872177 **License Number:** B751Q **Bus Number:** 15
Make of Body: IC Corporation **Year:** 2019 **Make of Chassis:** IC Corporation **Year:** 2020
Bus Type: C **Mileage:** 111700
Inspection Status: O **Inspected By:** Byron Goodman **PE:** 7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-3	There are any breaks, nicks or chips larger than 3/4 inch in diameter in the area covered by the wipers on the drivers' side
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
98-1-13	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.