

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	9/28/2023	Time:	11:38 AM		
Name of School Corporation:	SOUTH NEWTON SCHOOL CORP.			Corp ID:	565995		
Address of School Corporation:	13232 S 50 E						
City:	Kentland	Zip:	47951	County Number:	56		
VIN:	4DRBUC8P1PB138902		License Number:	25484	Bus Number:	2	
Make of Body:	IC Corporation	Year:	2022	Make of Chassis:	IC Corporation	Year:	2023
Bus Type:	C			Mileage:	11762		
Inspection Status:	O	Inspected By:	Tim Grayson	PE:	7558		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
70-1-4	There is any cracked glass to the immediate right or left of the driver
70-1-3	There are any breaks, nicks or chips larger than 3/4 inch in diameter in the area covered by the wipers on the drivers' side

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.