

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection Date: 9/28/2023 Time: 12:09 PM  
Name of School Corporation: SOUTH NEWTON SCHOOL CORP. Corp ID: 565995  
Address of School Corporation: 13232 S 50 E  
City: Kentland Zip: 47951 County Number: 56  
VIN: 1GB3G2BG5D1164105 License Number: 17814 Bus Number: 4M  
Make of Body: Starcraft Year: 2013 Make of Chassis: Chevrolet Year: 2013  
Bus Type: A1 Mileage: 121461  
Inspection Status: O Inspected By: Tim Grayson PE: 7558

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-1	Any headlight is inoperative
64-1-4	Any front turn signal does not function properly
64-1-2	A lens is cracked, missing or wrong color
36-1-2	The latch is not properly aligned, is loose or badly rusted
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
34-2-1	Both lamps are inoperative on low beam
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
55-2-4	Tie rod end movement is greater than 1/8 inch (rotational movement is acceptable)
31-2-1	Frame is deteriorated, cracked, broken or severely bent

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.