

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------------|------------------------|--------------|-------------------------|--------------|
| Type of Inspection: | Semi-Annual | Date: | 10/12/2023 | Time: | 11:12 AM |
| Name of School Corporation: | CENTERVILLE-ABINGTON COMM SCHS | Corp ID: | 898360 | | |
| Address of School Corporation: | 116 W SOUTH ST | | | | |
| City: | CENTERVILLE | Zip: | 47330 | County Number: | 89 |
| VIN: | 4UZABRDT7CCBA1198 | License Number: | 15159 | Bus Number: | 11 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2011 | Make of Chassis: | Freightliner |
| Bus Type: | C | Mileage: | 79882 | Year: | 2012 |
| Inspection Status: | R | Inspected By: | Jeremy Mason | PE: | 8139 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 23-1-5 | Any hanger, clamp or bracket is missing, loose or broken |
| 20-1-8 | If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly |
| 28-1-2 | The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment." |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.