

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 10/16/2023	Time: 8:41 AM	
Name of School Corporation: LAPORTE COMMUNITY SCHOOL CORP.	Corp ID: 464945		
Address of School Corporation: 1921 A St			
City: La Porte	Zip: 46350	County Number: 46	
VIN: 4DRBUAAN2EB495709	License Number: 5978	Bus Number: 25	
Make of Body: IC Corporation	Year: 2013	Make of Chassis: IC Corporation	Year: 2014
Bus Type: C	Mileage: 118937		
Inspection Status: O	Inspected By: Nathan Sherer	PE: 7029	

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-1	Any glass or glazing is broken through or missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.