

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	10/17/2023	Time:	9:54 AM
Name of School Corporation:	CRAWFORD CO. COMM. SCHOOL CORP	Corp ID:	131300		
Address of School Corporation:	5808 E Administration Rd				
City:	Marengo	Zip:	47140	County Number:	13
VIN:	1GBJG31K391164372	License Number:	81640	Bus Number:	86
Make of Body:	Collins Bus Corporation	Year:	2009	Make of Chassis:	Chevrolet
Bus Type:	A1	Mileage:	132013	Year:	2009
Inspection Status:	O	Inspected By:	Philip Lubbers	PE:	7703

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.