

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	10/17/2023	<b>Time:</b>	10:25 AM
<b>Name of School Corporation:</b>	CRAWFORD CO. COMM. SCHOOL CORP			<b>Corp ID:</b>	131300
<b>Address of School Corporation:</b>	5808 E Administration Rd				
<b>City:</b>	Marengo	<b>Zip:</b>	47140	<b>County Number:</b>	13
<b>VIN:</b>	1GB6G5BG0C1110997	<b>License Number:</b>	3443	<b>Bus Number:</b>	43
<b>Make of Body:</b>	Chevrolet	<b>Year:</b>	2012	<b>Make of Chassis:</b>	Chevrolet
<b>Year:</b>	2012	<b>Bus Type:</b>	A1	<b>Mileage:</b>	129126
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Philip Lubbers	<b>PE:</b>	7703

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-2	One (1) taillight or one (1) brake light does not function

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-1	There is no brake certification, or the certification has expired or is not signed

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**