# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 10/17/2023 Time: 10:25 AM

Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300

**Address of School Corporation:** 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:1GB6G5BG0C1110997License Number:3443Bus Number:43Make of Body:Chevrolet Year:2012Make of Chassis:Chevrolet Year:2012

Bus Type: A1 Mileage: 129126

Inspection Status: O Inspected By: Philip Lubbers PE: 7703

# Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

One (1) taillight or one (1) brake light does not function

#### **Violations - Out of Service**

# Inspection Code Description

8-2-1 There is no brake certification, or the certification has expired or is not signed

# **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.