REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 10/17/2023 Time: 10:59

Name of School
Corporation:

CRAWFORD CO. COMM. SCHOOL CORP
Corp ID: 131300

Address of School Corporation: 5808 E Administration Rd

City: Marengo Zip: 47140 County 13 Number:

Make of Body: GMC Year: 2011 Make of Collins Bus Chassis: Corporation Year: 2011

Bus Type: A2 Mileage: 204117

Inspection Status: O Inspected By: Philip Lubbers PE: 7703

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

95-1-15 See Notes: Any defect inspector deems a violation not listed

95-1-10 Does not move smoothly or rest solidly on the ground

Violations - Out of Service

<u>Inspection Code</u> <u>Description</u>

Warning lights fail to operate correctly

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.