REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection Date: 10/18/2023 Time: 10:21 AM

Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:4UZAAXCS47CW45066License Number:24636Bus Number:9Make of Body:Freightliner Year:2007Make of Chassis:Freightliner Year:2007

Bus Type: C Mileage: 93753

Inspection Status: A Inspected By: Philip Lubbers PE: 7703

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.