# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Registration | **Date:** | 10/18/2023 | **Time:** | 10:11 AM |
| **Name of School Corporation:** | EAST GIBSON SCHOOL CORPORATION | | | **Corp ID:** | 262725 |
| **Address of School Corporation:** | 941 S Franklin St | | | | |
| **City:** | Oakland City | **Zip:** | 47660 | **County Number:** | 26 |
| **VIN:** | 1HA6GUB79PN000353 | **License Number:** | N0353 | **Bus Number:** | 29 |
| **Make of Body:** | Chevrolet **Year:** 2023 | **Make of Chassis:** | Endera | **Year:** | 2024 |
| **Bus Type:** | A2 | **Mileage:** | 686 | | |
| **Inspection Status:** | A | **Inspected By:** | Bradley MIller | **PE:** | 7809 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

| Bus Type | Description |
|---|---|

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**