## REPORT OF SCHOOL BUS INSPECTION

Type of 9:28 Semi-Annual Time: Date: 10/25/2023 Inspection: AM Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL Corp ID: 141375 **Address of School Corporation:** 5494 E SR 58 County City: Elnora Zip: 47529 14 Number: License VIN: 1BAKGCPHOCF288177 NBND10 **Bus Number:** 10 Number: Make of Blue Bird Blue Bird Year: 2011 2012 Make of Body: Year: Corporation Chassis: Corporation Bus Type: С Mileage: 93318 Inspection Inspected R PE: 7703 Philip Lubbers Status: By:

## Violations - Rejected

13-1-1

Inspection Code	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Any clearance light is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.