

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 10/26/2023 **Time:** 11:00 AM
Name of School Corporation: DEKALB CO. CTL. UNTD. SCH DIST **Corp ID:** 171835
Address of School Corporation: 3326 CR 427
City: Waterloo **Zip:** 46793 **County Number:** 17
VIN: 4DRBUP1N4GB033772 **License Number:** 21890 **Bus Number:** 36
Make of Body: IC Corporation **Year:** 2016 **Make of Chassis:** IC Corporation **Year:** 2017
Bus Type: C **Mileage:** 59847
Inspection Status: O **Inspected By:** Eric Egbert **PE:** 7006

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
82-1-2	See Notes: Any defect inspector deems a violation not listed
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
67-1-2	Rims are bent or loose
33-1-2	The grill is missing
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
34-1-1	Any headlight is inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-3	Any tire is flat

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.