REPORT OF SCHOOL BUS INSPECTION

Type of 8:59 10/26/2023 Time: Re-Inspection Date: Inspection: AM Name of School Corporation: SOUTH HARRISON COMM, SCH. CORP Corp ID: 313190 **Address of School Corporation:** 315 S Harrison Dr County City: Corydon Zip: 47112 31 Number: License VIN: 4UZABRDT8BCAT7191 k00p **Bus Number:** 10 Number: Make of Thomas Built Buses, Year: 2009 Freightliner Year: Make of Body: 2009 Inc. Chassis: **Bus Type:** С Mileage: 192924 Inspected PE: **Inspection Status:** O Troy Boyd 5171

Violations - Rejected

Inspection Code Description

13-1-1 Any clearance light is missing, cracked, faded, wrong color, or inoperative

By:

68-1-1 Washers do not function properly in any manner

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.