REPORT OF SCHOOL BUS INSPECTION

9:02 Type of Semi-Annual 10/31/2023 Time: Date: Inspection: AM EASTERN HOWARD COMM, SCH. CORP 343480 Name of School Corporation: Corp ID: **Address of School Corporation:** 221 W Main St County City: Greentown Zip: 46936 34 Number: License VIN: 1T7YT4E20C1145214 155 **Bus Number:** 10 Number: Make of Thomas Built Buses, Year: 2010 Make of Body: Freightliner Year: 2012 Inc. Chassis: Bus Type: D Mileage: 69708 Inspected PE: 7018 **Inspection Status:** O Randy McPike By:

Violations - Rejected

<u>Inspection</u>	Description
<u>Code</u>	<u>Description</u>

Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

7-1-3 Air leak at proper connection

Violations - Out of Service

Inspection Code Description

46-2-3 Flip seat does not stay in the upright position when no passengers are seated

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.