

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|-----------------------------|------------------------|---------------|-------------------------|----------------|
| Type of Inspection: | Semi-Annual | Date: | 11/1/2023 | Time: | 11:43 AM |
| Name of School Corporation: | ISRAEL SCHOOL OF EXCELLENCE | | | Corp ID: | D913 |
| Address of School Corporation: | 7201 W 25TH AVE | | | | |
| City: | GARY | Zip: | 46406 | County Number: | 45 |
| VIN: | 4DRBUAAN09B681738 | License Number: | B410S | Bus Number: | 2 |
| Make of Body: | IC Corporation | Year: | 2007 | Make of Chassis: | IC Corporation |
| Year: | 2007 | Year: | 2009 | Year: | 2009 |
| Bus Type: | C | Mileage: | 174493 | PE: | 7029 |
| Inspection Status: | O | Inspected By: | Nathan Sherer | PE: | 7029 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 68-1-1 | Washers do not function properly in any manner |
| 28-1-4 | The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction. |
| 25-1-1 | Mirror or mirror backs that are loose or improperly mounted |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 41-2-1 | Interior is excessively dirty. (Excessive trash or dirt that would jeopardize the safety of students) |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.