

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	11/6/2023	<b>Time:</b>	11:30 AM		
<b>Name of School Corporation:</b>	ELWOOD COMMUNITY SCHOOL CORP.			<b>Corp ID:</b>	485280		
<b>Address of School Corporation:</b>	1306 N Anderson St						
<b>City:</b>	Elwood	<b>Zip:</b>	46036	<b>County Number:</b>	48		
<b>VIN:</b>	4DRBUAFP97B415352	<b>License Number:</b>	10795	<b>Bus Number:</b>	26		
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2006	<b>Make of Chassis:</b>	IC Corporation	<b>Year:</b>	2006
<b>Bus Type:</b>	B	<b>Mileage:</b>	85487	<b>PE:</b>	8139		
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Jeremy Mason				

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
90-1-2	The trash container is greater than a fourteen (14) quart capacity

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**