

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 11/8/2023	Time: 9:25 AM
Name of School Corporation: CENTRAL CATHOLIC HIGH SCHOOL	Corp ID: 79D415	
Address of School Corporation: 2410 S 9th St		
City: Lafayette	Zip: 47905	County Number: 79
VIN: 4DRBWAAR8DB335698	License Number:	Bus Number: 2
Make of Body: IC Corporation	Year: 2013	Make of Chassis: IC Corporation
Year: 2013	Year: 2013	
Bus Type: D	Mileage: 110738	
Inspection Status: R	Inspected By: Nate King	PE: 7421

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
52-1-2	Any shock absorber is leaking fluid
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.