REPORT OF SCHOOL BUS INSPECTION

9:31 Type of Semi-Annual Date: 11/9/2023 **Time**: Inspection: AM Name of School Corporation: DALEVILLE COMMUNITY SCHOOLS 181940 Corp ID: **Address of School Corporation:** 14300 W 2nd St County City: Daleville Zip: 47334 18 Number: License VIN: 4UZABRCS28CY69558 19042 **Bus Number:** 11 Number: Make of Thomas Built Buses, Year: 2006 Make of Body: Freightliner Year: 2008 Inc. Chassis: Bus Type: C Mileage: 127388 Inspected PE: **Inspection Status:** R Steve Spallinger 6921 By:

Violations - Rejected

Inspection Code Description

22-1-1 A dripping oil or fluid leak

The reflective material is placed anywhere other than on the front and rear, or both, of the bus between the warning lamps; each side beltline, seat line, or floor line or all three (3); outlining each required emergency exit; or across the rear of the bus directly above the rear bumper.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.