REPORT OF SCHOOL BUS INSPECTION

9:59 Type of Semi-Annual Date: 11/9/2023 **Time**: Inspection: AM DALEVILLE COMMUNITY SCHOOLS 181940 Name of School Corporation: Corp ID: **Address of School Corporation:** 14300 W 2nd St County City: Daleville Zip: 47334 18 Number: License VIN: 4UZAAXCS87CW37794 13239 **Bus Number:** Number: Make of Thomas Built Buses, Year: 2005 Make of Body: Freightliner Year: 2007 Inc. Chassis: Bus Type: C Mileage: 104125 Inspected PE: **Inspection Status:** O Steve Spallinger 6921 By:

Violations - Rejected

Inspection Code Description

The reflective material is placed anywhere other than on the front and rear, or both, of the bus between the warning lamps; each side beltline, seat line, or floor line or all three (3); outlining each required emergency exit; or across the rear of the bus directly above the rear bumper.

Violations - Out of Service

<u>Inspection Code</u> <u>Description</u>

Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.