

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Semi-Annual **Date:** 11/9/2023 **Time:** 9:59 AM  
**Name of School Corporation:** DALEVILLE COMMUNITY SCHOOLS **Corp ID:** 181940  
**Address of School Corporation:** 14300 W 2nd St  
**City:** Daleville **Zip:** 47334 **County Number:** 18  
**VIN:** 4UZAAXCS87CW37794 **License Number:** 13239 **Bus Number:** 6  
**Make of Body:** Thomas Built Buses, Inc. **Year:** 2005 **Make of Chassis:** Freightliner **Year:** 2007  
**Bus Type:** C **Mileage:** 104125  
**Inspection Status:** O **Inspected By:** Steve Spallinger **PE:** 6921

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
49-1-1	The reflective material is placed anywhere other than on the front and rear, or both, of the bus between the warning lamps; each side beltline, seat line, or floor line or all three (3); outlining each required emergency exit; or across the rear of the bus directly above the rear bumper.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**