REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	11/16/2023	**Time:**	12:28 PM
Name of School Corporation:	CLAY COMMUNITY SCHOOLS			**Corp ID:**	111125
Address of School Corporation:	PO Box 169				
City:	Knightsville	**Zip:**	47857	**County Number:**	11
VIN:	4DRBUC8NXLB872091	**License Number:**	23097	**Bus Number:**	69
Make of Body:	IC Corporation **Year:** 2019	**Make of Chassis:**	IC Corporation	**Year:**	2020
Bus Type:	C	**Mileage:**	114441		
Inspection Status:	O	**Inspected By:**	Byron Goodman	**PE:**	7008

Violations - Rejected

Inspection Code	Description
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
11-1-1	The front bumper does not extend to the edge of the fenders

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.