

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	11/16/2023	Time:	12:28 PM
Name of School Corporation:	CLAY COMMUNITY SCHOOLS	Corp ID:	111125		
Address of School Corporation:	PO Box 169				
City:	Knightsville	Zip:	47857	County Number:	11
VIN:	4DRBUC8NXLB872091	License Number:	23097	Bus Number:	69
Make of Body:	IC Corporation	Year:	2019	Make of Chassis:	IC Corporation
Year:		Year:		Year:	2020
Bus Type:	C	Mileage:	114441		
Inspection Status:	O	Inspected By:	Byron Goodman	PE:	7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
11-1-1	The front bumper does not extend to the edge of the fenders

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.