

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Post-Crash Inspection	<b>Date:</b> 11/21/2023	<b>Time:</b> 8:21 AM
<b>Name of School Corporation:</b> BATESVILLE COMM. SCHOOL CORP.	<b>Corp ID:</b> 696895	
<b>Address of School Corporation:</b> 626 N Huntersville Rd		
<b>City:</b> Batesville	<b>Zip:</b> 47006	<b>County Number:</b> 69
<b>VIN:</b> 4DRBUAAP4BB334498	<b>License Number:</b> B717M	<b>Bus Number:</b> 12
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2010	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2011	<b>Mileage:</b> 125628	<b>PE:</b> 6665
<b>Bus Type:</b> C	<b>Inspected By:</b> Chris Clark	
<b>Inspection Status:</b> O		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
67-1-2	Rims are bent or loose
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
63-1-1	Any tire has low air pressure

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**