REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection		Date:	12/6/2023	Time:	10:18 AM
Name of Schoo Address of Sch	I Corporation: SH	ENANDOAH S 5100 N Rai	CHOOL CORPO der Rd	ORATION	Corp ID:	333435
City:	Middletown	Zip:	47356		County Number:	33
VIN:	1T7YT4E2781104084		License Number:	32652	Bus Number:	36
Make of Body:	Thomas Built Buses, Yea	ar: 2008	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2008
Bus Type:	D		Mileage:	78286		
Inspection Status:	0	Inspected By:	Brandon Steffe	e	PE:	8247

Violations - Rejected

Inspection Code	Description
36-1-3	See Notes: Any defect inspector deems a violation not listed
11-1-7	See Notes: Any defect inspector deems a violation not listed
62-1-1	Any lens is cracked, missing, faded or of the wrong color
22-1-1	A dripping oil or fluid leak

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.