

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Re-Inspection	<b>Date:</b> 12/7/2023	<b>Time:</b> 2:45 PM
<b>Name of School Corporation:</b>	INCANDESCENT TRANSPORTATION SOLUTIONS	<b>Corp ID:</b> 45007Z
<b>Address of School Corporation:</b>	2158 45TH ST	
<b>City:</b> HIGHLAND	<b>Zip:</b> 46322	<b>County Number:</b> 45
<b>VIN:</b> 4UZABRDTX9CAE3354	<b>License Number:</b> B490T	<b>Bus Number:</b> 4
<b>Make of Body:</b> Thomas Built Buses, Inc.	<b>Year:</b> 2008	<b>Make of Chassis:</b> Freightliner
<b>Year:</b> 2009	<b>Mileage:</b> 128406	<b>PE:</b> 7558
<b>Bus Type:</b> C	<b>Inspected By:</b> Tim Grayson	
<b>Inspection Status:</b> R		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
7-1-3	Air leak at proper connection
24-1-1	The bus body has rust or rusted through areas which may weaken the body
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.